



73% Increase In Claim Award Yields Metal Roof Upgrades

APPLICATIONS

STANDING SEAM
METAL

MANUFACTURER

BERRIDGE

PRODUCTS

24 GA. STEEL

SIZE

132 SQUARES

PROBLEM

This bank in Arlington, TX, came to us with a leaking roof. Upon our inspection, we not only found hail damage, but we also brought to the bank's attention that they had an inferior product that was installed incorrectly from the beginning. We recommended that they to file an insurance claim that came back at \$127,658.00 for full replacement- this was not sufficient enough to cover the scope of work the bank needed. We have seen this many times before and we assured the customer we could help them get what they deserved.

SOLUTION

Our solution was to educate the customer to be the best advocate for themselves with the Claims Adjuster. Knowing the right things to say to a claims adjuster is critical when looking for a fair claim award. Once the customer receives the deserved claim amount, we recommend installing a better material, components, and custom roll forming the material on-site to achieve exquisite functional and aesthetic desires.

RESULTS

Through our assistance, the bank received a final award amount of \$221,479.00. The amount they received allowed this bank to upgrade their roof system significantly! The previous roof didn't give off that trustable, commanding look that a bank needs to possess. When you drive by, you go, "wow," that is a beautiful metal roof. The details are sharp, and the components are seamless. This bank will be worry free of leaks and protected by this strong standing seam metal roof for years to come!

